



**RICS**

the mark of  
property  
professionalism  
worldwide

**DAUPHINE**  
UNIVERSITÉ PARIS

# COBRA 2010

## **The Construction, Building and Real Estate Research Conference of the Royal Institution of Chartered Surveyors**

**Held at Dauphine Université, Paris, 2-3 September 2010**

ISBN 978-1-84219-619-9

© RICS

12 Great George Street  
London SW1P 3AD  
United Kingdom

[www.rics.org/cobra](http://www.rics.org/cobra)

September 2010

The RICS COBRA Conference is held annually. The aim of COBRA is to provide a platform for the dissemination of original research and new developments within the specific disciplines, sub-disciplines or field of study of:

### **Management of the construction process**

- Cost and value management
- Building technology
- Legal aspects of construction and procurement
- Public private partnerships
- Health and safety
- Procurement
- Risk management
- Project management

### **The built asset**

- Property investment theory and practice
- Indirect property investment
- Property market forecasting
- Property pricing and appraisal
- Law of property, housing and land use planning
- Urban development
- Planning and property markets
- Financial analysis of the property market and property assets
- The dynamics of residential property markets
- Global comparative analysis of property markets
- Building occupation
- Sustainability and real estate
- Sustainability and environmental law
- Building performance

## The property industry

- Information technology
- Innovation in education and training
- Human and organisational aspects of the industry
- Alternative dispute resolution and conflict management
- Professional education and training

## Peer review process

All papers submitted to COBRA were subjected to a double-blind (peer review) refereeing process. Referees were drawn from an expert panel, representing respected academics from the construction and building research community. The conference organisers wish to extend their appreciation to the following members of the panel for their work, which is invaluable to the success of COBRA.

Rifat Akbiyikli	Sakarya University, Turkey
Rafid Al Khaddar	Liverpool John Moores University, UK
Ahmed Al Shamma'a	Liverpool John Moores University, UK
Tony Auchterlounie	University of Bolton, UK
Kwasi Gyau Baffour Awuah	University of Wolverhampton, UK
Kabir Bala	Ahmadu Bello University, Nigeria
Juerg Bernet	Danube University Krems, Austria
John Boon	UNITEC, New Zealand
Douw Boshoff	University of Pretoria, South Africa
Richard Burt	Auburn University, USA
Judith Callanan	RMIT University, Australia
Kate Carter	Heriot-Watt University, UK
Keith Cattell	University of Cape Town, South Africa
Antoinette Charles	Glasgow Caledonian University, UK
Fiona Cheung	Queensland University of Technology, Australia
Sai On Cheung	City University of Hong Kong
Samuel Chikafalimani	University of Pretoria, South Africa
Ifte Choudhury	Texas A and M University, USA
Chris Cloete	University of Pretoria, South Africa
Alan Coday	Anglia Ruskin University, UK
Michael Coffey	Anglia Ruskin University, UK
Nigel Craig	Glasgow Caledonian University, UK
Ayirebi Dansoh	KNUST, Ghana
Peter Davis	Curtin University, Australia
Peter Defoe	Calford Seaden, UK
Grace Ding	University of Technology Sydney, Australia
Hemanta Doloi	University of Melbourne, Australia
John Dye	TPS Consult, UK
Peter Edwards	RMIT, Australia
Charles Egbu	University of Salford, UK
Ola Fagbenle	Covenant University, Nigeria
Ben Farrow	Auburn University, USA
Peter Fenn	University of Manchester, UK
Peter Fewings	University of the West of England, UK

Peter Fisher	University of Northumbria, UK
Chris Fortune	University of Salford, UK
Valerie Francis	University of Melbourne, Australia
Rod Gameson	University of Wolverhampton, UK
Abdulkadir Ganah	University of Central Lancashire, UK
Seung Hon Han	Yonsei University, South Korea
Anthony Hatfield	University of Wolverhampton, UK
Theo Haupt	Cape Peninsula University of Technology, South Africa
Dries Hauptfleisch	University of the Free State, South Africa
Paul Holley	Auburn University, USA
Danie Hoffman	University of Pretoria, South Africa
Keith Hogg	University of Northumbria, UK
Alan Hore	Construction IT Alliance, Ireland
Bon-Gang Hwang	National University of Singapore
Joseph Igwe	University of Lagos, Nigeria
Adi Irfan	Universiti Kebangsaan Malaysia, Malaysia
Javier Irizarry	Georgia Institute of Technology, USA
Usman Isah	University of Manchester, UK
David Jenkins	University of Glamorgan, UK
Godfaurd John	University of Central Lancashire, UK
Keith Jones	University of Greenwich, UK
Dean Kashiwagi	Arizona State University, USA
Nthatsi Khatleli	University of Cape Town, South Africa
Mohammed Kishk	Robert Gordon's University, UK
Andrew Knight	Nottingham Trent University, UK
Scott Kramer	Auburn University, USA
Esra Kurul	Oxford Brookes University, UK
Richard Laing	Robert Gordon's University, UK
Terence Lam	Anglia Ruskin University, UK
Veerasak Likhitrungsilp	Chulalongkorn University, Thailand
John Littlewood	University of Wales Institute, Cardiff, UK
Junshan Liu	Auburn University, USA
Champika Liyanage	University of Central Lancashire, UK
Greg Lloyd	University of Ulster, UK
S M Lo	City University of Hong Kong
Mok Ken Loong	Yonsei University, South Korea
Martin Loosemore	University of New South Wales, Australia
David Manase	Glasgow Caledonian University, UK
Donny Mangitung	Universitas Tadulako, Malaysia
Patrick Manu	University of Wolverhampton, UK
Tinus Maritz	University of Pretoria, South Africa
Hendrik Marx	University of the Free State, South Africa
Ludwig Martin	Cape Peninsula University of Technology, South Africa
Wilfred Matipa	Liverpool John Moores University, UK
Steven McCabe	Birmingham City University, UK
Annie McCartney	University of Glamorgan, UK
Andrew McCoy	Virginia Tech, USA
Enda McKenna	Queen's University Belfast, UK
Kathy Michell	University of Cape Town, South Africa
Roy Morledge	Nottingham Trent University, UK

Michael Murray	University of Strathclyde, UK
Saka Najimu	Glasgow Caledonian University, UK
Stanley Njuangang	University of Central Lancashire, UK
Henry Odeyinka	University of Ulster, UK
Ayodejo Ojo	Ministry of National Development, Seychelles
Michael Oladokun	University of Uyo, Nigeria
Alfred Olatunji	Newcastle University, Australia
Austin Otegbulu	
Beliz Ozorhon	Bogazici University, Turkey
Obinna Ozumba	University of the Witwatersrand, South Africa
Robert Pearl	University of KwaZulu, Natal, South Africa
Srinath Perera	Northumbria University, UK
Joanna Poon	Nottingham Trent University, UK
Keith Potts	University of Wolverhampton, UK
Elena de la Poza Plaza	Universidad Politécnica de Valencia, Spain
Matthijs Prins	Delft University of Technology, The Netherlands
Hendrik Prinsloo	University of Pretoria, South Africa
Richard Reed	Deakin University, Australia
Zhaomin Ren	University of Glamorgan, UK
Herbert Robinson	London South Bank University, UK
Kathryn Robson	RMIT, Australia
Simon Robson	University of Northumbria, UK
David Root	University of Cape Town, South Africa
Kathy Roper	Georgia Institute of Technology, USA
Steve Rowlinson	University of Hong Kong, Hong Kong
Paul Royston	Nottingham Trent University, UK
Paul Ryall	University of Glamorgan, UK
Amrit Sagoo	Coventry University, UK
Alfredo Serpell	Pontificia Universidad Católica de Chile, Chile
Winston Shakantu	Nelson Mandela Metropolitan University, South Africa
Yvonne Simpson	University of Greenwich, UK
John Smallwood	Nelson Mandela Metropolitan University, South Africa
Heather Smeaton-Webb	MUJV Ltd. UK
Bruce Smith	Auburn University, USA
Melanie Smith	Leeds Metropolitan University, UK
Hedley Smyth	University College London, UK
John Spillane	Queen's University Belfast, UK
Suresh Subashini	University of Wolverhampton, UK
Kenneth Sullivan	Arizona State University, USA
Joe Tah	Oxford Brookes University, UK
Derek Thomson	Heriot-Watt University, UK
Matthew Tucker	Liverpool John Moores University, UK
Chika Udeaja	Northumbria University, UK
Basie Verster	University of the Free State, South Africa
Francois Viruly	University of the Witwatersrand, South Africa
John Wall	Waterford Institute of Technology, Ireland
Sara Wilkinson	Deakin University, Australia
Trefor Williams	University of Glamorgan, UK

Bimbo Windapo	University of Cape Town, South Africa
Francis Wong	Hong Kong Polytechnic University
Ing Liang Wong	Glasgow Caledonian University, UK
Andrew Wright	De Montfort University, UK
Peter Wyatt	University of Reading, UK
Junli Yang	University of Westminster, UK
Wan Zahari Wan Yusoff	Universiti Tun Hussein Onn Malaysia, Malaysia
George Zillante	University of South Australia
Benita Zulch	University of the Free State, South Africa
Sam Zulu	Leeds Metropolitan University, UK

**In addition to this, the following specialist panel of peer-review experts assessed papers for the COBRA session arranged by CIB W113**

John Adriaanse	London South Bank University, UK
Julie Adshead	University of Salford, UK
Alison Ahearn	Imperial College London, UK
Rachelle Alterman	Technion, Israel
Deniz Artan Ilter	Istanbul Technical University, Turkey
Jane Ball	University of Sheffield, UK
Luke Bennett	Sheffield Hallam University, UK
Michael Brand	University of New South Wales, Australia
Penny Brooker	University of Wolverhampton, UK
Alice Christudason	National University of Singapore
Paul Chynoweth	University of Salford, UK
Sai On Cheung	City University of Hong Kong
Julie Cross	University of Salford, UK
Melissa Daigneault	Texas A&M University, USA
Steve Donohoe	University of Plymouth, UK
Ari Ekroos	University of Helsinki, Finland
Tilak Ginige	Bournemouth University, UK
Martin Green	Leeds Metropolitan University, UK
David Greenwood	Northumbria University, UK
Asanga Gunawansa	National University of Singapore
Jan-Bertram Hillig	University of Reading, UK
Rob Home	Anglia Ruskin University, UK
Peter Kennedy	Glasgow Caledonian University, UK
Anthony Lavers	Keating Chambers, UK
Wayne Lord	Loughborough University, UK
Sarah Lupton	Cardiff University
Tim McLernon	University of Ulster, UK
Frits Meijer	TU Delft, The Netherlands
Jim Mason	University of the West of England, UK
Brodie McAdam	University of Salford, UK
Tinus Maritz	University of Pretoria, South Africa

Francis Moor	University of Salford, UK
Issaka Ndekugri	University of Wolverhampton, UK
John Pointing	Kingston University, UK
Razani Abdul Rahim	Universiti Teknologi, Malaysia
Linda Thomas-Mobley	Georgia Tech, USA
Paul Tracey	University of Salford, UK
Yvonne Scannell	Trinity College Dublin, Ireland
Cathy Sherry	University of New South Wales, Australia
Julian Sidoli del Ceno	Birmingham City University, UK
Keren Tweeddale	London South Bank University, UK
Henk Visscher	TU Delft, The Netherlands
Peter Ward	University of Newcastle, Australia

# The Development of a Condition Survey Protocol (CSP) 1 Matrix for Visual Building Inspection

A.I. Che-Ani

Department of Architecture, Faculty of Engineering and Built Environment, Universiti Kebangsaan Malaysia, 43600 UKM Bangi, Selangor, MALAYSIA. [adiirfan@gmail.com](mailto:adiirfan@gmail.com)

A.S. Ali

Department of Building Surveying, Faculty of the Built Environment, University of Malaya, 50603 Kuala Lumpur, MALAYSIA. [asafab@um.edu.my](mailto:asafab@um.edu.my)

M.M. Tahir

Department of Architecture, Faculty of Engineering and Built Environment, Universiti Kebangsaan Malaysia, 43600 UKM Bangi, Selangor, MALAYSIA. [designaar@gmail.com](mailto:designaar@gmail.com)

N.A.G. Abdullah

Department of Architecture, Faculty of Engineering and Built Environment, Universiti Kebangsaan Malaysia, 43600 UKM Bangi, Selangor, MALAYSIA. [akmal.goh@gmail.com](mailto:akmal.goh@gmail.com)

N.M. Tawil

Department of Architecture, Faculty of Engineering and Built Environment, Universiti Kebangsaan Malaysia, 43600 UKM Bangi, Selangor, MALAYSIA. [nmtawil@gmail.com](mailto:nmtawil@gmail.com)

## Abstract

Building inspection is one of the key components of building maintenance. The primary purpose of performing a building inspection is to evaluate the building's condition. Without inspection, it is difficult to determine a built asset's current condition, so failure to inspect can contribute to the asset's future failure. Traditionally, a longhand survey description has been widely used for property condition reports. Surveys that employ ratings instead of descriptions are gaining wide acceptance in the industry because they cater to the need for numerical analysis output. These kinds of surveys are also in keeping with the new RICS HomeBuyer Report 2009. In this paper, we propose a new assessment method, derived from the current rating systems, for assessing the building's condition and rating the seriousness of each defect identified. These two assessment criteria are then multiplied to find the building's score, which we called the Condition Survey Protocol (CSP) 1 Matrix. Instead of a longhand description of a building's defects, this matrix requires concise explanations about the defects identified, thus saving on-site time during a building inspection. The full score is used to give the building an overall rating: Good, Fair or Dilapidated. Our overall findings reflect the reliability of the CSP1 Matrix.

*Keywords:* assessment matrix, asset management, building inspection, building survey, condition assessment, eco-sustainable toilet, rating system, reasonable property condition, survey protocol, visual inspection

## 1.0 Introduction

The purpose of conducting a building inspection is to assess the building's condition. The inspection is a key means of identifying a building's defects. Defects usually display their symptoms before getting worse and causing building failure. It is therefore crucial for building inspections to be performed many



times in an asset's life cycle. This is also supported by the philosophy of *Dasar Pengurusan Aset Kerajaan* (DPAK), the Malaysian Government Asset Management Policy and Total Asset Management (TAM) Manual. These two documents underpin the Malaysian government's asset management plan, depicted in Figure 1. Specifically, the TAM Manual outlines the need to conduct building inspections to fulfil the requirement for continuous evaluation throughout an asset's life cycle.




Figure 1: Maintenance Transformation Approach – Towards TAM (Mat-Deris, 2009)

Traditionally, building surveyors have primarily relied on descriptive longhand surveys. This means that surveyors recorded every detail by hand when performing on-site building inspections. This is an acceptable practice when applied to building survey work, especially if the property being inspected is considered to be in unreasonable condition; for example, it could be an abandoned, vacant and/or dilapidated property. This approach is highlighted in the Royal Institution of Chartered Surveyors (RICS) HomeBuyer Service 2009 (3<sup>rd</sup> Edition Practice Notes), which came into effect beginning 1 July 2009. These practice notes mention that the building survey report is usually longer, more detailed and more technical than the RICS HomeBuyer Report.

As the HomeBuyer Service points out, there is a need for a quick and practical approach to performing building inspections under reasonable property conditions. According to the RICS (2009), the

reporting procedure for a RICS building inspection produces a shorter and less detailed report in a standardised format. In addition to this report, a condition rating is included; this special feature standardises the report and provides a quick overview of the condition of the entire property. This approach is useful when doing routine building inspections during the normal cycle of maintenance, which includes an annual general building inspection.

Taking this as our point of departure, we developed the Condition Survey Protocol (CSP) 1 Matrix as an assessment method for evaluating building condition. This method was specifically developed for first-line, visual building inspection work. It comprises three protocols: Protocol 1 is defined as visual inspection, Protocol 2 as Non-Destructive Testing (NDT) and Protocol 3 as sample-taking and/or Destructive Testing (DT). The primary features of this matrix are the rating forms. To test whether or not the matrix was practical and effective, the matrix was used to evaluate the building condition of ECSTRUCT<sup>TM</sup>, an eco-sustainable toilet. This paper highlights the application of the CSP1 Matrix to the evaluation of ECSTRUCT<sup>TM</sup>'s condition and presents the survey's findings.

## **2.0 ECSTRUCT<sup>TM</sup>: Eco-Sustainable Toilet**

Public toilets in Malaysia are seen as outmoded. The conventional public toilet (usually an island or freestanding type) faces problems with hygiene, health, security, vandalism, privacy, ventilation, lighting and aesthetics. ECSTRUCT<sup>TM</sup>, an eco-sustainable toilet, is an innovative, ecologically friendly and sustainable public toilet building. Such buildings are sometimes placed in the category of micro-architecture. The inventor of this product is Dr. Azimin Samsul M. Tazilan, from the Department of Architecture, School of Engineering and Built Environment, Universiti Kebangsaan Malaysia. The design seeks to solve the various issues mentioned above and is uniquely developed to be a sustainable, zero-energy building that provides maximum comfort and has a functional but aesthetically pleasing look. This toilet has also received numerous prestigious research awards, both locally and overseas; among others, it won the Gold Medal at the British Invention Show in 2007. Figure 2 shows a 3-D view and front view of ECSTRUCT<sup>TM</sup>.

The property on which ECSTRUCT<sup>TM</sup> stands is located in Pulau Langkawi, Kedah. The building was built for the Ministry of Science, Technology and Innovation (MOSTI). Construction began in 2007

and was completed in 2008. The building inspection was carried out in June 2009, when the building had been in operation for approximately 1 year. The property was therefore considered to be in reasonable condition. The building inspection work carried out on this property is actually part of the building's performance evaluation process, conducted in support of and compliance with the DPAK and TAM manuals.



Figure 2: ECSTRUCT™: Eco-Sustainable Toilet (This research)

### 3.0 Condition Survey Protocol (CSP) 1 Matrix

The rating criteria for building inspections are still being developed. One of the earliest contributions was made by Pitt (1997), followed by Alani et al. (2001), Che-Ani (2008a, 2008b, 2009), Mahmood (2009) and RICS (2009). Pitt (1997) and Alani et al. (2001) proposed rating criteria that could be applied to any type of building. Che-Ani (2008a, 2008b, 2009) provided criteria that were specifically designed to assess the condition of timber houses. Mahmood (2009) developed the Navil Matrix©, which is currently used in building inspections. The most recent criteria were developed by RICS (2009), who established the 3-rating system for the inspection of homes classified as having reasonable property conditions.

With the aim of contributing to the development of building inspection rating systems, this research concentrates on providing rating criteria that can be used to assess a building's defects. Our system gathers two sets of data, namely, the condition of the building and the seriousness of a building's defects, which can be analysed to provide a rating of the building's overall condition. As Protocol 1

(visual inspection) forms the basis of this rating system, we named the system the Condition Survey Protocol (CSP) 1 Matrix. The CSP1 Matrix was developed as a rating tool for a reasonable property condition assessment. The matrix is also suitable for all types of buildings because the data input relies on the condition and damage assessments. While the elemental breakdown of each building might vary from building to building, this does not prevent the format of the matrix from being able to accommodate any condition of survey work. The goals behind the CSP1 Matrix are:

- i. To enable the surveyors to collect data within shortest possible time by avoiding descriptive, longhand write-ups during fieldwork;
- ii. To record the existing defects of the building, the main source of data, by assessing the condition and assigning priority to each defect recorded;
- iii. To obtain an overall rating of the building's condition. The proposed remedial work is not the main concern of this matrix. Moreover, the repair work usually cannot be carried out immediately after the survey's completion because of budget constraints. Therefore, the validity of any proposed remedial work would need to be reconfirmed later; and
- iv. To use the numerical rating acquired from the survey work to perform statistical analysis.

The data required for the CSP1 Matrix are the condition and the priority assessments, as shown in Tables 1 and 2. Each numerical score (1 to 5) is accompanied by a scale value and description. This will help surveyors to rate the building's defects and to determine the exact condition implied by the scale values. The scale values and their descriptions depend on the maintenance standard of the building being evaluated. For instance, the scale can be made more stringent than the example provided here. The examples given in Tables 1 and 2 are the most basic scales used in the CSP1 Matrix.

Table 1: Condition Assessment Protocol 1

Condition	Scale Value	Description
1	Good	Minor Servicing
2	Fair	Minor Repair
3	Poor	Major Repair/Replacement
4	Very Poor	Malfunction
5	Dilapidated	Damage/Replacement of Missing Part

Table 2: Priority Assessment

Priority	Scale Value	Description
1	Normal	Functional; cosmetic defect only
2	Routine	Minor defect, but could become serious if left unattended
3	Urgent	Serious defect, doesn't function at an acceptable standard
4	Emergency	Element/structure doesn't function at all; OR Presents risks that could lead to fatality and/or injury

Each recorded defect is assigned a condition and priority rating. Each rating is then multiplied to determine the total score for each defect. The total score is then matched with the matrix, as shown in Table 3. The scores range from 1 to 20. A colour (green, yellow or red) is then applied to indicate the score in each of the 3 parameters: Plan Maintenance (1 to 4), Condition Monitoring (5 to 12) and Serious Attention (13 to 20), as shown in Table 4. This method of analysis makes it easy to identify the level of seriousness of each defect recorded during the building inspection.

Ratings for the individual defects must be assigned carefully and according to the preset maintenance standards and/or defect definitions used by the surveyors/clients. This will reduce the risk of misinterpreting the seriousness of the defects identified, especially when dealing with red-coded defects. It is important to keep in mind that the red-coded defects should be dealt with first; this will influence the overall building rating and highlight the individual defects that are posing extreme danger to the building. This will also help the surveyor to identify the risk of individual defects and provide clients with well-informed defect summaries.

Table 3: The matrix

Scale		Priority Assessment			
		E 4	U 3	R 2	N 1
Condition Assessment	5	20	15	10	5
	4	16	12	8	4
	3	12	9	6	3
	2	8	6	4	2
	1	4	3	2	1

Table 4: The descriptive value according to score

No	Matrix	Score
1	Planned Maintenance	1 to 4
2	Condition Monitoring	5 to 12
3	Serious Attention	13 to 20

After scoring every defect, we calculated the overall building rating, which summarises the building's condition. The score of each defect is added up and divided by the total number of defects to get the overall building rating. The building is then rated Good, Fair or Dilapidated, according to the score (out of 20). Table 5 shows the overall building ratings.

Table 5: Overall building ratings

No	Building Rating	Score
1	Good	1 to 4
2	Fair	5 to 12
3	Dilapidated	13 to 20

All of the information gathered for the CSP1 Matrix is recorded in the Schedule of Building Condition form, shown in Table 6. For reporting purposes, the CSP1 Matrix comprises a photograph box, a defect plan tag and an executive summary, as shown in Figures 3 through 6. The discussion of the reporting procedure follows in the next section of this paper.

#### 4.0 Results and discussion

The ECSTRUCT<sup>TM</sup> building was used as a case study to test the reliability of the CSP1 Matrix. The building inspection was carried out on 26 June 2009 in clear and fair weather conditions. The inspection was carried out during a 2-hour period, and visual inspection was the primary survey method. The inspection started with the building's exterior and concluded with the building's interior. A top-down and clockwise surveying technique was adapted for this building inspection. This procedure is one of the surveying techniques suggested by Hollis (2000) and Hoxley (2002) and is designed to prevent surveyors from overlooking any defects. During the time of inspection, there were no users inside the building.

The description of each defect is concise and straightforward. Standard terms are used where applicable. The main idea is to describe what the defect is. In the Schedule of Building Condition form, the description of each defect is accompanied by an image in the photograph/sketch box (see Figures 3 and 4) and its location in the defect plan tag (see Figure 5). For reporting purposes, the defects were divided according to their location: Exterior, Male and Female. The defects were grouped together if they belonged to the same building element and their repair work would likely be done at the same time. For example, defects no. 2 and 3 were combined because they belong to the same building element, namely,

the rainwater collector. The repair work for these defects, which would include fixing the gap and resealing the collector, is therefore likely to be done at the same time.

Our findings are shown in Table 6. The total number of defects was 29, with a total score of 127. The sum of the defect scores was divided by the number of defects to obtain the total score. In this study, the total score was 4.38, which merits a ‘Good’ overall building rating. The information from Table 6 was then transferred to the ‘Executive Summary’ sheet, as shown in Figure 6. This sheet highlights 4 items, namely, the Property Information, the summary of the CSP1 Matrix, the Overall Building Rating and the Recommendation.

In this study, the overall building rating for ECSTRUCT™ was established; this rating reflects the existing condition of the property. The key information in the CSP1 Matrix is the Schedule of Building Condition. The colour code adopted allows quick identification of a defect’s categorisation. This permits a client who wants to know whether the inspector found any defects that need serious attention to easily locate the ‘red’-rated defects. Based on our findings, the CSP1 Matrix is practical for making evaluations of reasonable condition properties. However, the CSP1 Matrix still needs to be tested on buildings of a larger scale to determine whether it produces reliable results regardless of property size.

**Table 6: BUILDING CONDITION ASSESSMENT for ECSTRACT, LANGKAWI, KEDAH**  
**Schedule of Building Condition (CSP1 Matrix)**

NO.	AREA	DEFECTS	Condition Survey Protocol (CSP) 1				
			Condition Assessment [a]	Priority Assessment [b]	Matrix A'lysis [c] (a x b)	Photo No. / (Sketch No.)	Defect Plan Tag
A	EXTERIOR	<b>Rainwater outlet</b>					
		1 Front outlet: Blocked by dried leaves	2	2	4	1	1
		<b>Rainwater collector</b>					
		2 Back collector: Had small gap	2	2	4	2	2
		3 Back collector: Sealant fail	1	2	2	3	3
		<b>Gutter at both sides</b>					
		4 Back gutter: Blocked by dried leaves	2	2	4	4	4
		<b>Water tank</b>					
		5 Water tank (front): Distorted	3	4	12	5	5
		6 Water tank (back): Sagging and leaking	3	4	12	6	6
		<b>Water tank support</b>					
		7 Supporting bar: Corroded	2	2	4	7	7
		<b>Distribution board (DB)</b>					
		8 Cover: Does not open and close properly	1	1	1	8	8
B	MALE						
	First cubicle (Disabled)	<b>Water closet (WC)</b>					
		9 Flush does not function	2	2	4	9	9
		<b>Door</b>					
	Second cubicle	10 Misaligned	2	2	4	10	10
		11 Does not close and lock properly	2	2	4	11	11
		<b>Water closet (WC)</b>					
	Circulation	12 Flush does not function	2	2	4	12	12
		<b>Tap</b>					
		13 Functions, but has low water pressure	2	2	4	13	13
		<b>Hand dryer</b>					
		14 Does not function and is not affixed to wall	2	2	4	14	14
		<b>Dustbin</b>					
		15 Not properly affixed to floor and sagging	1	2	2	15	15
		<b>Sink</b>					



		Sink tap 1: Functions, but has low water pressure	2	2	4	16	16
		Sink tap 2: Does not function	2	2	4	17	17
		Outlet: Blocked	3	2	6	18	18
		<b>Lamp</b>					
		Does not function	2	2	4	19	19
		<b>Vegetation area</b>					
		Vegetation: No longer present	2	2	4	20	20
C	<b>FEMALE</b>						
	First cubicle (Disabled)	<b>Tap</b>					
		Functions, but has low water pressure	2	2	4	21	21
	Second cubicle	<b>Tap</b>					
		Pipe disconnected and has low water pressure	2	3	6	22	22
		<b>Door</b>					
		Does not close properly	2	2	4	23	23
	Circulation	<b>Hand dryer</b>					
		Not properly affixed to wall	2	2	4	24	24
		<b>Dustbin</b>					
		Not properly affixed to floor	1	2	2	25	25
		<b>Sink</b>					
		Sink tap 1: Functions, but has low water pressure	2	2	4	26	26
		Sink tap 2: Functions, but has low water pressure	2	2	4	27	27
		<b>Lamp</b>					
		Does not function	2	2	4	28	28
		<b>Vegetation area</b>					
		Vegetation: No longer present	2	2	4	29	29
<b>Total marks [d] (<math>\Sigma</math> of c)</b>					127		
<b>Number of defects [e]</b>					29		
<b>Total score (d/e)</b>					<b>4.38</b>		
<b>Overall building rating</b>					<b>Good</b>		

**Limitation(s):**

- The rooftop was not inspected because there was no safe access during the time of inspection.


<div>Photograph / Sketch No.</div> <div></div>	2	Level	Roof		
		Location	Roof		
		Element/ Component	Rainwater collector		
	CSP1				
	Condition	Priority	Matrix	Colour	
	2	2	4		
	Defect description				
	Back collector: Had small gap				
	Possible causes				
	Poor construction				
	Remarks				
None					

Figure 3: Example 1 – Photograph (This research)


Photograph / Sketch No.	6	Level	Roof		
	Location	Roof			
	Element/	Water tank			
	Component				
	CSP1				
	Condition	Priority	Matrix	Colour	
	3	4	12		
	Defect description				
	Water tank (back): Sagging and leaking				
	Possible causes				
	Poor construction. Poly tanks cannot be directly exposed to weather conditions. There is also no full support at the bottom of the tank.				

Figure 4: Example 2 – Photograph (This research)




Figure 5: Layout for defect plan tag (This research)

**BUILDING CONDITION SURVEY FOR ECSTRACT™,  
PULAU LANGKAWI, KEDAH DARUL AMAN**

**CONDITION SURVEY PROTOCOL (CSP) 1**

**EXECUTIVE SUMMARY**

**1.0 Property Information**

**Building Address** : ECSTRACT™ Pulau Langkawi, Kedah Darul Aman  
**Owner Name** : Ministry of Science, Technology and Innovation (MOSTI)  
**Date of inspection** : 26.06.2009  
**Weather** : Clear and Fair

**2.0 Condition Survey Protocol (CSP) 1 Matrix**

No.	Matrix	Score	Color Code	Finding(s)
1.	Planned Maintenance	1 to 4		25
2.	Condition Monitoring	5 to 12		4
3.	Serious Attention	13 to 20		0
<b>Total Defects</b>				<b>29</b>

**3.0 Overall Building Rating**

No.	Building Rating	Score
1.	Good	1 to 4
2.	Fair	5 to 12
3.	Dilapidated	13 to 20

Total marks - 127  
Number of defects - 29  
Total score - 4.38  
**Overall building rating - Good**

**4.0 Recommendation**

This building is in Good condition.

However, the total score is close to 5, indicating that, if the defects identified in this inspection, especially the ones coded yellow, are left unattended, the building's condition will fall to Fair.

Therefore, it is recommended that periodical inspections be carried out on this building and that any actions recommended by this report are carried out to prevent further dilapidation to the building.

Figure 6: Executive summary of the CSP1 Matrix (This research)

## **5.0 Conclusion**

Building inspection requires skill in identifying defects and familiarity with reporting procedures. It primarily involves on-site work and preparation of a report. This paper focuses on the latter. Traditionally, longhand descriptions have been employed for reporting building inspection work. These are time consuming, particularly during site inspections. The CSP1 Matrix has been developed to shorten this process, thus shortening on-site inspection time. As the case study has shown, the CSP1 Matrix achieved its objective and proved to be a reliable and practical assessment method for building inspections performed under reasonable property conditions. However, the CSP1 Matrix needs further use before it will be clear whether it is suitable for inspections of medium and large properties. It is likely that the CSP1 Matrix is not suitable for unreasonable property conditions, where more detailed descriptions of the defects are required, particularly for the preparation of a Building Survey report.

## **Acknowledgements**

The authors would like to thank all parties involved in this research, particularly our funding agency, Universiti Kebangsaan Malaysia. Credit also goes to Navil Mahmood (Professional Building Surveyor), who has established the Navil Matrix©, which became the basis for the development of the CSP1 Matrix©.

## **References**

- Alani, A. M.; Petersen, A. K.; Chapman, K. G. (2001). *Applications of The Developed Quantitative Model In Building Repair and Maintenance – Case Study*. Journal of Facilities. Volume 19 Number 5/6. pp. 215-221. MCB University Press Limited.
- Che-Ani, A.I.; Zaharim, A.I.; Zain, M.F.M; Tawil, N.M; Surat, M. (2009). “Timber Defects in Building: A Study of Telapak Naning, Malacca, Malaysia”. *WSEAS Transactions on Environment and Development*. Issue 1 Vol. 5 Jan. 09. pp. 109-118.

- Che-Ani, A.I.; Ramly, A.; Zain, M.F.M; Tawil, N.M.; Hashim, A.E. (2008a). "Assessing The Condition of Traditional Khmer Timber Houses In Cambodia – A Priority Ranking Approach". *Journal of Building Appraisal*. Vol. 4 No. 2 Summer 2008. pp. 87-102.
- Che-Ani, A.I.; Zaharim, A.; Md-Darus, Z.; Tawil, N.M. (2008b). "*The Formulation of Evaluating Timber Defects As A Tool For Building Survey*". World Scientific & Engineering Academy and Society (WSEAS) International Conference on Cultural Heritage & Tourism (CUHT) 2008. 22-24 July 2008. Heraklion, Crete Island, Greece. pp. 125-130.
- Hollis, M.; Gibson, C. (2000). *Surveying Buildings*. 4th Edition. Coventry: RICS Books. Imprint.
- Hoxley, M. (2002). *Condition Inspections of Residential Property: A Procedural Framework*. Journal of Structural Survey. Volume 20 Number 1. pp. 31-35. MCB University Press Limited.
- Mahmood, N. (2009). "Building Surveyors in Private Sector – Condition Assessment". Presentation Note. Malaysia Building Surveyors Jamboree 2009. University Science Malaysia (USM). Organized by The Institution of Surveyors Malaysia (ISM) and University Technology MARA (UiTM) Perak. 4-6 December 2009.
- Mat-Deris, M.S. (2009). *Malaysian Total Asset Management Approach*. Presentation during Building Surveyors Role in Public Work Department (JKR) Seminar. Organized by JKR. JKR Headquarter, Jalan Sultan Salahudin, Kuala Lumpur. 29 June 2009.
- Pitt, T. J. (1997). Data Requirements For The Prioritization of Predictive Building Maintenance. *Journal of Facilities*. Volume 15 Number 3/4. pp. 97-104. MCB University Press Limited.
- RICS (2009). *RICS HomeBuyer Service 2009 – 3<sup>rd</sup> Edition Practice Notes*. Residential Property Group of the Royal Institution of Chartered Surveyors (RICS). United Kingdom: Coventry.